

Work Order ID 62036

Wednesday, September 15, 2010 10:18:20 A



Page 1

Item ID: D206-559-023

Accept



Setup Start



Revision ID:

Stop



Item Name: Bearpaw

Start Date: 9/15/2010 Start Qty: 5.00



Cust Item ID:

Required Date: 9/16/2010 Req'd Qty: 5.00



Customer:

Reference: ECN 10-613

Approvals: Process Plan: mf Date: 10-9-15

Tooling:

Date:

Run Start



QC: Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
IIN-D206-559	J -PRELIM								

200

0.00



Packaging

Memo

0.00

Packaging

PULL FROM STOCK D206-559-023
B 41731 X 5
REMOVE AN4-15A BLOTS AND REPLACE WITH AN4-20A

MEL WILL MAKE AN ADJ

UPDATE PAPERWORK AND LABELS TO CHANGE 7

210

QC4- 100% Inspect kits for completeness

0.00



QC

Memo

0.00

Quality Control

S. Wolke

10/9/10 52

x5

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 62036

Wednesday, September 15, 2010 10:18:20 A

Page 2

Item ID: D206-559-023

Accept

Revision ID:

Item Name: Bearpaw

Start Date: 9/15/2010 Start Qty: 5.00

Required Date: 9/16/2010 Req'd Qty: 5.00

Reference: ECN 10-613

Cust Item ID:



Customer:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start

Stop

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
220 	Identify as per dwg & Stock Location: <u>12</u>	0.00							
Packaging	Memo	0.00							
Packaging	ID AND STOCK UNDER NEW BATCH								
230 	QC21- Final Inspection - Work Order Release	0.00							
QC	Memo	0.00							
Quality Control									

10/09/17
MF
10-9-16

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries




Wednesday, September 15, 2010 10:18:19 AM

[illegible]

Required Date: 9/16/2010

Required Qty: 5.00

Comments: IPP Rev: E 04.02.17 Tolerance added to Step 3 KJ/JLM
IPP Rev: F 07-01-02 Was K10006 JLM
IPP Rev: G 08-09-19 Added step 2 JLM Verified By: EC
IPP Rev: H New Manufacturing Method 08-10-29 JLM Verified By: EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
AN4-15A 		Purchased	No				Each	323.0000	12	-60		10/9/16	
Bolt													
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				ST338				112					
				ST358				211					
					112905			12					
					114784			21					
					115108			78					
					115371			100					
AN4-20A 		Purchased	No				Each	678.0000	12			10/9/16	
Bolt													
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				ST359				678					
					104016			662					
					16895			16					
D206-559-023 		Manufactured	No				Each	6.0000				10/9/16	
Bearpaw													
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				FG012				6					
					39081			1					
					41734			5					

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

REFERENCE ONLY

5.0 PARTS LIST (D206-559 REV. K) 32.7 PARTS LIST (ICA-D205-559 REV. 2)





Qty -011	Qty -013	Qty -021	Qty -023	Qty -031	Qty -033	Qty -113	Part Number	Description
X							D206-559-011	Bearpaw Kit 206 A/B
	X						D206-559-013	Bearpaw Kit 206 L/L1/L3/L4/407
		X					D206-559-021	Narrow Bearpaw Kit 206 A/B
			X				D206-559-023	Narrow Bearpaw Kit 206 L/L1/L3/L4/407
				X			D206-559-031	Wearplate Kit
					X		D206-559-033	Wearplate Kit
						X	D407-559-113	Large Bearpaw Kit 206 L/L1/L3/L4/407
4	6	4	6				D2182B050	RUBBER CUSHION
8	12	8	12			20	D2274	RADIUS BLOCK
2							D2435	19" X 16" BEARPAW
	2						D2432F	19" X 24" BEARPAW
		2					D2671	13" X 16" BEARPAW
			2				D2672F	13" X 24" BEARPAW
4	6	4	6				D2438	CLAMP
8	12	8	12				D2529	WASHER
	6		6				D2732-050	RUBBER CUSHION
						2	D3456-1	WASHER
					2		D3859-041	WEARPLATE
				2			D3860-041	WEARPLATE
						2	D4010-041	BEARPAW ASSEMBLY
						8	D4011-1	CLAMP, SHORT
						2	D4011-3	CLAMP, LONG
						8	D4011-5	CLAMP, SHORT (OEM)
						10	D4012-1	CUSHION
						2	AN4C10A	BOLT
8	12	8	12	8	12		AN4-17A	BOLT
8	12	8	12	8	12		AN4-20A	BOLT (WAS AN4-15A)
						4	AN4C13A	BOLT
						8	AN4C15A	BOLT
						8	AN4C17A	BOLT
16	24	16	24				AN960JD416	WASHER (OR NAS1149D0463J)
8	12	8	12	8	12		MS21042L4	NUT (OR MS21042-4)
						20	MS21043-4	NUT
				8	12		NAS1149D0463J	WASHER (OR AN960JD416)
2		2					QS200M44S	CLAMP

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY: 
D. SHEPHERD (DE # 02)

DATE: 10.06.30
CERT. NO.: SH92-17
ISSUE NO.: 7

DESIGN		DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN			
CHECKED		DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9527	SHEET 2 OF 2
APPROVED		TITLE	SCALE
DE APPR.		BOLT CHANGE	NTS
DATE	10.06.30	COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	